THE NETHERLANDS

Organizations Contacted:

Nederlands Normalisatie - Instituut (NNI)
Polakweg 5
Rijswijk (ZH)
The Netherlands

Tel [redacted]
Fax: 070-32-123

Ir. A.J. De Roos
Director General
Directoraat-General van de Arbeid
CIS Department
Postbus 69
2270 MA Voorburg
The Netherlands

2501045646

Source: https://www.industrydocuments.ucsf.edu/docs/tzdk0000

Standards Documents Obtained/Consulted Thus Far:

NEN 1087

Ventilation in dwellings. Requirements. (1979 and amended in 1981)

NEN 1089

Ventilation in school buildings. Requirements. (1986)

NEN 2687

Air leakage of dwellings. Requirements (1987)

NEN 2688

Air leakage in commercial buildings (in preparation)

Draft standard for "Whole Building" ventilation regulation

In addition, ILO/CIS is being contacted to determine what, if any, workplace exposure limits exist with respect to hazardous chemicals and other indoor pollutants.

2501045647

Source: https://www.industrydocuments.ucsf.edu/docs/tzdk0000

Key Indoor Ventilation Standards:

-- NEN 1087, ventilation in dwellings:

Minimum ventilation requirements for dwellings of 7 dm^3/s per person, plus recommended ventilation rates for individual rooms in relation to floor area.

[See attachment from AIVC Technical Note 30 (Sept. 1990) further describing Dutch ventilation standards.]

250104548

Source: https://www.industrydocuments.ucsf.edu/docs/tzdk0000

Ongoing Research Relating To IAQ Issues:

CONTACT: Zweers, Tunnie
Preller, Liesbeth

ADDRESS: Agricultural University of Wageningen
Department of Environmental Health
P.O. Box 238
Wageningen
The Netherlands

TEL: 31-08270-83376
FAX: 31-08270-82782

SPECIFIC OBJECTIVES:

Finding causes of indoor climate and health problems in buildings.

PROJECT DETAILS:

Questionnaires will be distributed to office workers enquiring about work-related symptoms of ill health, indoor climate related complaints, job satisfaction, etc.

2501045649

Source: https://www.industrydocuments.ucsf.edu/docs/tzdk0000